

Company Name: Cricklade Road Management Company Limited

Inspector Name: Thomas Dellow MIRPM AssocRICS and Kamila Zak

Inspection Date: 16 January 2024

Purpose

This site inspection record is used when undertaking regular site inspections and is solely for the purpose of recording and monitoring the common (communal) parts on behalf of the above company.

What Is Included

The below report comments on the general condition of the interior and exterior communal parts (where applicable) as they were found at the time of this inspection.

Please note: This inspection is carried out visually by the property manager or a competent person instructed by the property manager and should not be used for any other purpose than to comment and record the general state and condition of the common (communal) parts that are inspected during a routine site visit. Where further investigation, testing or remedial work is required, a competent person is instructed by the property manager.



Internal Inspection	Acceptable	Not Acceptable	N/A	Comments	Action
Entrances (Main doors)	✓			The main doors are secure	None
Hallway (Communal Lobbies and Stairs)	✓			Hallways are clear and free of obstruction	None
Lighting (Standard and Emergency Lighting)	✓			The lighting appeared in good visual condition and operation	None
Internal Doors (Compartment Doors)	✓			The internal doors were accessible	None
Cupboard Doors (Electrical Cupboard Doors)	✓			Cupboard doors are locked and secure	None
Windows (Communal Windows)	✓			Communal windows are secure	None
Signage (Communal Notices)	✓			Signage is up to date	None
Additional Comments					None



BLOCK MANAGEMENT LTD


PROFESSIONAL PROPERTY MANAGEMENT

External Inspection	Acceptable	Not Acceptable	N/A	Comments	Action
Exterior Structure (The Building)	✓				None
Guttering (Gutters and Fascia)	✓				None
Roofing (Tiles and Cladding)	✓				None
Communal Grounds (Gardens and Common Areas)	✓				None
Bin Store (Waste Disposal Areas)		✓		There are items of fly-tipping near the bin store which require removal	Review
Car Park (Vehicle Parking)	✓				None
Bike Store (Bicycle Areas)	✓				None
Additional Comments					None

Entrances (Main Doors)



Hallway (Communal Lobbies and Stairs)



Lighting (Standard and Emergency Lights)



Internal Doors (Compartment Doors)



Cupboard Doors (Electrical Cupboard Doors)



Windows (Communal Windows)



Signage (Communal Notices)



Additional Photos




Exterior Structure (The Building)




Guttering (Gutters and Fascia)



Roofing (Tiles and Cladding)




Communal Grounds (Gardens and Common Areas)




Bin Store (Waste Disposal Area)



Car Park (Vehicle Parking)



Bike Store (Bicycle Areas)



Additional Photos

